



This chart shows how low OH<sup>-</sup> content GE fused quartz transmits more energy compared to "wet" varieties of the material. The IR energy transmission of fused quartz is affected by the presence or absence of OH<sup>-</sup> absorption band at 2.73μm. The overall effect is an increase in the efficiency of IR heating through the quartz.

[Close Window](#)